



- NOTES:-
1. ON MACHINES WITH SERIAL N°S 3780 TO 3854 THE CORD CONNEXION COLOUR CODE DOES NOT CONFORM TO THE ABOVE.
 2. THESE RADIO INTERFERENCE SUPPRESSION COMPONENTS ARE "N.R.B." ITEMS.
 3. THE FIELD ADJUSTMENT ON THE MOTOR & THE LINK ON THE MOTOR CONN. BLOCK MUST BOTH BE SET TO THE REQUIRED VOLTAGE RANGE.

CIRCULATION	GENERAL
	Suffix
Amend.	
PAPER	W