LOW VOLTAGE DISCONTINUOUS LAMP SIGNALLING

USING TELEPHONE No.332 (AUTO AREAS ONLY)

N1887
ISSUE A

SCHEMATIC



WIRING



NOTES

1. Remove strap between telephone terminals T1 and T2.
2. RELAY SET. To be made up locally, consists of
   - 1. Relay No.8552
   - 1. Capacitor, paper No.7710
   - 1. Rectifier element 4/6A
   - 1. Mounting No.151/2A
   - 1. Bracket mtg. AZ
   - 1. " " CZ
   - 1. Relay cover AP
   - 1. Block terminal 21/5

P.O.T.D.D. TD 1.4.1.	ISSUES		
PAPER: W			
CIRCULATION CB. & AUTO	A	New Format	22-2-68
		F.E.Troke S1	13-2-62