


# Maintenance News

Index

ISSUE 1

1981



Editor : Ron Quinney (ES5.4.3)

Published by BTHQ/NE/ES5.4.3 Room 1230,  
207 Old Street  
LONDON EC1V 9PS  
01-739 3464 Ext. 7695

Maintenance News  
ISSN 0143-6627

Produced by Management Communications (BTHQ/PR3.1.5)

# Maintenance News

Index  
ISSUE 1 1981

This *Maintenance News* index is divided alphabetically under subject headings, and articles are listed under these in publication date order.

Space has been left to allow readers to update their own index as future articles are published. Where the content of an article is not clear from its title, clarification is given in brackets.

For completeness some articles have more than one entry in the index, for example, *Those Gas Leaks (MN 7 p10)* appears under 'Underground' and 'Safety'.

The intention is to re-issue the index every two years.

*Editor.*

	Issue	page		Issue	page
<b>Coinboxes</b>			Answer to the 3300B Indicator Problem	10	25
Digital Timer for Coinbox Mechanisms	2	20	Secrets of Line 6 (A51 Telephone Instrument Faults)	12	3
Call Office Maintenance in Midland Region	6	6	Automatic Callmakers	12	10
News on Call Offices	10	16	Keyphones and MF Signalling – Glasgow Area’s Tester	13	30
Call Offices – Customers and Complaints	13	2	Key System 4+12 – Proprietary SBS	16	29
Maintenance Thoughts on New Coinboxes	18	27	How Much Does A Fault Report Cost Now ?	17	9
			Special Range Telephones – Maintenance	17	25
			Herald Call Connect System	19	30
			Microphone Inset 21A	19	18
<b>Customers’ apparatus</b>			<b>Data and Datel</b>		
PABXs – See ‘Exchanges PABX’			Introduction to Data Transmission and Datel Services	6	12
No Access Cards – A108 (m)	1	12	Data Transmission PO Datel Services	7	16
Subscribers Apparatus Maintenance Policy	2	17	Experimental Packet Switched Service – The Facts	8	30
Keyphones	3	26	All will be TOLD	9	20
Trimphone Performance – Noisy Transmitter Inset No 15	3	28	Dataplex	10	11
New Training Courses for Faultsmen	3	29	Datel Test Centres	11	25
The New Style Residential Telephone (Compact Telephone)	4	6	Packet Switching Goes Public	15	36
Handling Electronic Items of Customers Apparatus	5	9	Data Customer Service Officers	17	24
Batteries in Telephone Apparatus	6	8	Datel’s New Modem 27A	18	3
Identifying Fault Prone PBXs	6	9	DATEC Organisation	19	8
The TSR – Friend or Foe ?	6	31			
How Much Does A Fault Report Cost ?	7	21			
Overcoming Problems Loudspeaking Telephone 4D	8	16			
The PMBX 11	9	16			
Reliability of Customer Apparatus	10	15			
Dangerous Earthing at Subscribers’ Premises	10	15			
Answering Sets	10	21			
2					

**Exchanges – general**

			What use is your Traffic Recorder	12	21
PIP5, PIP6 and PIP7	1	20	A Call Monitoring Equipment From Cardiff	13	27
Centralised Maintenance of Exchanges (EMUs)	2	6	What is TCSE ?	14	20
Regenerator No 5A	3	10	LTR's Computer-aided Fault Reference Centre	14	22
Computer-aided Maintenance Project – CAMP	3	12	Metering (Metering Improvement Plans)	15	13
Measurement and Analysis Centres – MAC	3	22	Transit Network Performance (ASSET)	15	30
Why Reference Centres ?	3	23	MAC – Experience at the sharp end	16	27
Cleaning London's Exchanges	5	20	Traffic Patterns for MAC	16	32
Subscribers' Meters – New Performance Statistics	5	22	Cleaner Telephone Exchanges	17	13
The Transit Network	6	20	Small Exchange Replacement – The Scottish		
Internal Self-inflicted Wounds (Exchange Planning			Solution (UXE Exchanges)	17	15
Shortcomings)	6	23	How the Isle of Man Solved a Problem (Transit		
Blast Wrecks Exchange (Bishopwearmouth Gas			Repeat Attempt Monitor)	17	18
Explosion)	7	9	MASS for MAC (MAC Software)	17	22
Metering Faults (Various Causes)	7	29	Isolation : Cable (Single Cable Outlet Exchanges)	18	2
Recorded Information Services – New Equipment on			London's Sector Switching Centres (SSC's)	18	17
the way (Equipment Announcer 11A)	7	32	Jump(er) to it	19	18
Ringin, Pulsing and VF Machines	8	6			
Beware of Test Jack Lamps (Tester TRT 172)	8	10			
Processors and Software for Telecommunications	8	14			
CSS1 – Simpler Operating Plus a Better Service to					
Customers	9	5			
The Mini SSAC9	9	9			
MAC Updated – First Measurement and Analysis			<b>Exchanges – Crossbar TXK</b>		
Centre Planned for early 1977	11	4	Any Crossbar Exchange in your Area ? (Exchange		
Quality of Service (TIP's)	11	8	Types)	3	15
STD Metering – Revenue losses due to faults	11	15	TXK Exchanges – Fault Diagnosis by Computer	3	20
SERT – A Small Exchange Route Tester	12	6	Crossbar Exchanges – Some Maintenance Aspects	4	24
Tester TRT 219A – for Coin and Fee Checking Relay			Crossbar Exchanges – Some Further Aspects of		
Sets	12	20	Maintenance	5	29

	Issue	page		Issue	page
Some Aspects of Congestion in TXK1	7	25	Non-Director International Equipment Maintenance	14	25
Sticking Relays at TXK1s	7	28	International Direct Dialling (Quality of Service)	15	14
Computer Assistance in SSC Maintenance (TXK1)	10	30			
TXK1 Local Exchanges	14	27			
London's Sector Switching Centres – SSCs	18	17			
Computer Aid to Exchange Maintenance (TXK4)	18	28			
The Headless Cross Mk1P (Maintenance in a TXK1 GSC)	19	10	<b>Exchanges – Strowger TXS</b>		
Crossbar Spares	19	22	Night Routining	1	16
			Seeking Out the Rogue Switch (RANCH)	1	18
			Partially Skipped Gradings (See also <i>MN10</i> p15)	4	18
			Changes in Acceptance Testing for Strowger Exchanges	4	21
			FNF's Matter	5	35
			Location of Microphonic Noise in Strowger Exchanges	6	24
<b>Exchanges – digital (System X) TXD</b>			Delay Action Fuse for Motor Uniselectors	6	25
System X (Basic Principles)	13	16	Remote Printout for CFDE's (See also <i>MN14</i> p8)	10	24
New Equipment Practice – TEP1E	18	23	Maintenance Philosophy for Strowger Exchanges	12	8
Britain's First Digital Exchange	19	15	Block Routines for Strowger Exchanges	12	9
System X in Baynard House	19	13	Replacement of directors (TRT 13 'MOST')	14	5
			Call Failure Detection Equipment (See also <i>MN10</i> p24)	14	8
			MF4 at TXS	15	19
			Future of Strowger	16	4
			LTR Makes the MOST of its RT 13s	17	14
			Wiper-to-bank Noise in Strowger Exchanges	18	9
<b>Exchanges – International Direct Dialling</b>					
Maintaining The International Telephone Service	6	28			
International Subscriber Dialling	10	7			
Signalling Display Equipment in the ETE (Now BTI)	14	23			

**Exchanges – electronic TXE2**

Troubles with TXE2	4	19
TXE2 Matrix Tester to be Provided	7	27
Call Failure Counting Equipment for TXE2	9	19
TXE2 Isolations	15	18

Common Control PABXs – Problems	7	23
The IBM 3750 Stored Program Control PABX	11	17
Electronic PABXs (Type Description)	12	12
Type Approval of Customers PABXs	15	20
Monarch 120 – A New Call Connect System	15	22
Type Approval of Customers SPC Systems	16	12

**Exchanges – TXE 4**

Introducing TXE4	10	3
The Woodley and Broughton Strikes (Lightning Damage)	18	1
London’s Maintenance Approach to TXE4	19	6

**Equipment repair**

Introducing RESCs	4	29
Servicing Precision Test Equipment	7	26
Electronic Repairs by FacD	10	23
Automatic Test Systems (ATS)	13	4
Area Repair Centres (ARC)	17	1

**Exchanges – TXE4A**

Introducing TXE4A	16	6
-------------------	----	---

**General**

Don’t cut ‘em off (Customer Complaint Procedures)	1	12
Insulation Damage to Jumpers	1	14
Tell us what you think of TIs	1	28
Defects and Difficulties – The A646 Procedure	2	32
Engineering Changes of Practice Committees	4	5
Running TIs (Special Maintenance Information)	7	13

**Exchanges – PABX**

New PABXs	2	22
Private Switched Networks – Some Maintenance Problems	5	26

	Issue	page
Reliability – Terminology and Measurement	8	4
MOS Chips – Handle With Care	8	22
Save It – In the Telecommunications Business (Energy Conservation)	11	3
TIs and You	12	5
Q Points the way (TI Indexes)	13	18
High Grade Precautions	14	11
A Welcome Reduction in BUMPH! (TI Distribution)	14	17
Those Replacement Diagrams (Requisition Procedures)	14	33
Service to the Customer (Quality of Service Measurements)	15	1
Post codes Rule OK (Post code Description)	15	8
Keeping the Wheels Turning (Motor Transport Maintenance)	15	26
How Quality is Assured (Quality Assurance – QA)	15	33
Care For a Chip (Handling ICs)	17	4
What is an IEEE Bus ?	17	10
Green Mean Caution (High Grade Precautions)	17	20
Planned Work (A60s)	18	5
Don't Plan a Service Interruption (A60 Pitfalls)	18	16
Channel Island Restoration Plans	18	22
New Equipment Practice – TEP1E	18	23
BT Act 1981 – and the future	19	1
Tester Co-ordination Working Party (TCWP)	19	11

**International Direct Dialling – see  
'Exchanges IDD'**

**Local lines (see also 'Underground' and  
'Overhead')**

Local Line Insulation Routining	1	4
Pulse Testing in the Local Line Network	1	7
Locator 6A for Faults in Buried Polyethylene Cables	2	26
Self-inflicted Wounds (UG Working Party Faults)	2	29
Plant Protection Officers	2	30
Radial System Recommended on Housing Estates	5	16
Speaker Circuits at Cabinets and Pillars	9	18
Local Underground Line Plant Improvement in Scotland	11	7

**Maintenance News**

Introducing Maintenance News	1	1
On Reflection ( <i>MN9</i> )	19	34



**Overhead maintenance**

Dropwire Fault Locating and Renewal	2	25
Safety Overhead	4	8

**Power**

Maintaining Power Supplies	2	4
Modular Power Plants	8	11
Cooling Off in Apparatus Rooms (Refrigeration Plants)	9	22
The Statistics of Power Maintenance	12	13
A Change in Battery Maintenance (SG and Voltage Measurements)	13	15
PO High Voltage Sub-stations	15	28
High Voltages— Some Problems and Answers (Working in Sub-stations)	16	13

**Prestel**

Prestel in London	17	19
-------------------	----	----

**Private Automatic Branch Exchanges – see 'Exchanges – PABX'****Private Circuits – see 'Special services'****Radio**

Microwave Relay Systems (Protection Switching Tester 190)	3	30
Radiopaging	5	10
Radiophone Service	6	14
Microwave Radio System Maintenance – Transferring the Emphasis (New Maintenance Methods)	13	25
Satellite Earth Stations	14	1
Radiopaging Nationwide	17	5
Digital Radio Systems	19	26

**Repair Service Controls**

Battery Contact Testing on 56-type Desks	1	13
Testing for CSH or Loop	1	13
High Capacity Test Junctions on 56-type Desks	1	14
Plant Reliability Surveys (A51's)	2	18
Connecting NU Tone to out-of-order Business Lines	2	24
Test Desk Design Trials	3	24

	Issue	page		Issue	page
Customer Fault Reports which Prove RWT	4	8	<b>Special services (including private circuits) – see also 'Data and Data1'</b>		
A New Procedure for PCO Fault Reports (T222 Forms)	4	17	Private Switched Networks – Some Maintenance Problems	5	26
Test Desk Design Trials at Newcastle-upon-Tyne	5	4	PCM Network for BBC Sound Broadcasts	8	19
The Future of RSCs	7	19	Private Circuit Maintenance	8	28
Desk Top Equipment for RSCs	8	8	Private Circuit Fault Reporting – MTR Method 'an improvement'	9	12
How Much Does a Fault Cost Now ?	14	9	Testing 'Wires Only' Telegraph Private Circuits	10	22
Computerised A51s	16	17	The Independant Local Radio Service	10	26
Service Triangle Helps Midland Reach PCA25 Target	17	3	Measuring Private Circuit Performance – A New Scheme (TIP 2A)	13	28
A Strategy for Improving the Repair Service	18	12	International Leased Circuits	16	9

## Safety

Gas I (Safety Precautions)	4	12
Those Gas Leaks (Safety Precautions)	10	15
Dangerous Earthing at Subscribers' Premises	7	10
Asbestos – PO Takes Action	12	12
PO Engineering Safety Guide – RG 41	13	24
Engineering Safety	15	9
PO High Voltage Sub-stations	15	28
High Voltages – Some Problems and Answers (Working in Sub-Stations)	16	13
Engineering Safety – 2 (Safety Aids)	16	15

## Stores

Why we reject 12 000 requisitions every year	7	12
The Label Business	16	23
Stamp It Out (Piece Part Requisitions)	16	31

**Submarine cable systems**

Teaching Aids to Fault Locating on Submarine Systems	13	20
Submarine Cable Systems	14	28
Cable Ships Keep Alert	19	19

**Telex**

Routiners and Testers for Telex Exchanges	2	8
Selector Bank Failures in Telex Exchanges	2	9
A New Teleprinter for the Telex Service? (ITT 2300)	9	10
SPC for Telex Switching	13	22
Some Telex TIPS (Quality of Service Measurement)	16	21
Modernising Telex (SPC Telex)	18	10

**System X – see 'Exchanges – digital'****Telegraphs**

Now for an Interruption (Short breaks on MCVF)	1	22
TG 2402 – A New Tester for Measuring Telegraph Distortion	4	27
TDM and the Telegraph Network (184 Channel TDM)	5	24
Improving Telex Service Signal Equipment	7	34
New MCVF Systems Use Modern Technology	11	21
Mercury-wetted Relays in Telegraph Transmission Equipment – An Occasional Problem	12	22
Seven Fifteen Twenty-three . . . ? (New Teleprinters)	15	16
A New Private Automatic Telegraph Branch Exchange – PATBX2A	16	20

**Training**

New Training Courses for Faultsman (Customers Apparatus)	3	29
Training – a £47 Million Investment in 1976/77	13	6
Teaching Aids to Fault Locating on Submarine Systems	13	20
Training at POTTC Stone (New Courses)	14	4
Teach Yourself Elementary Electronics (The 'Parva Pack')	14	30

**Transmission – general**

New Transmission Fault Recording Procedures	1	24
Service Protection Network	2	10
NCC News (NNCC and RNCC description)	5	13
NCC News (SPN Switching)	6	33
NCC News (Coaxial Line Link Failure Rates)	7	14
NCC News (Service Restoration Times)	8	13
NNCC – A Finger on the Network’s Pulse (NNCC function)	8	18
How’s your Transmission Efficiency? (TEOs)	9	13
A Personal View of Transmission Inefficiency – by a TEO	9	25
NCC News (Hypergroup Performance)	10	29
A Day in the Life of the Service Protection Network	17	21
ABC Alarms in East Anglia	19	28

**Transmission – audio**

The Negative Impedance Repeater	14	32
The Negative Impedance Repeater – Part 2	15	27

**Transmission – digital (see also ‘Transmission – PCM’)**

The Digital Network – A glimpse into the future	15	4
---	----	---

Optical Fibre Line System’s Maintenance	18	20
Digital Transmission – The Basic PCM System	18	24
Digital Line Systems	19	23
Digital Multiplexing and Coding	19	24
Digital Radio Systems	19	26

**Transmission – HF**

Transmission Reference and Analysis Console	1	26
Introduction of Hypergroup Reference Pilots	2	14
Working Party Overloads on Coaxial Cable Links	2	16
Maintaining the New 60 MHz Cables	6	10
60 MHz Systems and their Maintenance	12	18
CEL 4000 – Supervisory and Fault Locating Methods on 12 MHz Coaxial Line Systems	13	9
New Line Transmission Test Equipment	17	11

	Issue	page		Issue	page
<b>Transmission – PCM (see also ‘Transmission – digital’)</b>			Gas ! (Gas Safety Precautions)	4	12
PCM Problems (including Lightning)	3	5	Cleaning Up the Underground in Coventry	4	14
PCM Network for BBC Sound	8	19	Trunk and Junction Cable Maintenance	5	32
Digital Programme Equipment	19	4	Maintaining the New 60 MHz Cable	6	10
			Those Gas Leaks ! (Safety Precautions)	7	10
			Mac the Life (Direct Lead-ins)	8	23
			Housing Estates on Trial (Direct Lead-ins)	8	26
			Breaking the Moisture Barrier	9	15
			Speaker Circuits at Cabinets and Pillars	9	18
			Locating Air Leaks in Cable Sheaths	10	18
			Injection-moulding for Closing Joints	10	19
			Local Underground Plant Improvement in Scotland	11	7
			Wot ! No Spares ? (Cable Manufacture)	11	16
<b>Transmission – television</b>			Cable Pressurisation Equipment	11	23
Lightning Protection on Broadcast Video Links	3	7	Julie – A Dial Before You Dig Service	12	1
Managing The Broadcast Service Network	5	6	Chambers of Horror (Cable Chambers)	12	2
The PO Wideband Cable TV Distribution System	6	18	Keeping up the Pressure (Pressurisation of Defective Cable)	13	1
Television Network Switching for the IBA	13	12	Finding PCM Carrying Quads	14	12
Closed Circuit TV – New Testers	16	22	Local Underground Plant in Wales (Improvement)	14	15
			Fault Location for Underground Lines – MOLE	14	16
			Terminating on Cabinets	14	18
			Seal of Approval (Duct Seals)	15	9
<b>Underground (see also – ‘Local Lines’)</b>			Plant Requiring Attention – A1024 Reports	15	35
Local Line Insulation Routining	1	4	Better Joints for Local Lines	16	1
Pulse Testing in the Local Line Network	1	7	PETs on Cables (Pulse Echo Tester)	16	24
A New Method of Monitoring Cable Pressures	1	11	Second Harmonic Testing of Coaxial Cables	18	6
Self-inflicted Wounds (UG Working Party Faults)	2	29			
Plant Protection Officers	2	30			
Keeping Tabs on Local Underground Fault Costs	4	10			

## Notes



British  
TELECOM