


NOTES:-

1. Key No.303A or 304A & the requisite number of parts 1/SPL/325 (Key Plungers complete) to be requisitioned separately, if required.
2. Spring 1 of Cradle Switch Spring-Set assembly is adjacent to the mounting.
3. Earlier issues of Tele.No.308C.B. minus cord have coil, induction No.22 instead of No.27. The external connexions are the same but the winding resistances and turns ratios of the two coils are different.
4. Differences between MKS.1, 2 & 2A of Tele.No.308C.B. minus cord are:-
 - MK.1 has Receiver, Inset No.1L in Tele.No.164.
 - MK.2 has Receiver, Inset No.2P in Tele.No.164.
 - MK.2A as for MK.2 but has Switch Bracket & Plungers of improved design.


TELEPHONE No. 308 C.B. MINUS CORD
 COMBINED HANDSET TELEPHONE (With Magneto Bell)
 FOR USE IN C.B. & AUTO AREAS ON CERTAIN EXTENSION
 PLANS WITH, OR WITHOUT, KEYS No.303 A OR 304 A.

N. 408
 ISSUE B



Label diagram to be to dimensions given.

EXPLANATORY



→ Indicates direction of windings on coil, induction.

P.O.T.D.D. TD 1.4.1				
PAPER: W CIRCULATION GENERAL	ISSUES			
		B	NEW FORMAT	25 - 1 - 68
		A	COIL INDUCTION No. 27 WAS No. 22	13 - 3 - 50
			E.S.R., SI.	10 - 6 - 39