


NOTES:-

1. Key No.303A or 304A & the requisite number of parts 1/SPL/325 (Key Plungers complete) to be requisitioned separately, if required.
2. Spring 1 of Cradle Switch Spring-Set assembly is adjacent to the mounting.
3. Earlier issues of Tele.No.308C.B. minus cord have coil, induction No.22 instead of No.27. The external connexions are the same but the winding resistances and turns ratios of the two coils are different.
4. Differences between MKS.1, 2 & 2A of Tele.No.308C.B. minus cord are:-
  - MK.1 has Receiver, Inset No.1L in Tele.No.164.
  - MK.2 has Receiver, Inset No.2P in Tele.No.164.
  - MK.2A as for MK.2 but has Switch Bracket & Plungers of improved design.


TELEPHONE No. 308 C.B. MINUS CORD  
 COMBINED HANDSET TELEPHONE (With Magneto Bell)  
 FOR USE IN C.B. & AUTO AREAS ON CERTAIN EXTENSION  
 PLANS WITH, OR WITHOUT, KEYS No.303A OR 304A.

N. 408  
 ISSUE B



Label diagram to be to dimensions given.

EXPLANATORY



→ Indicates direction of windings on coil, induction.

P.O.T.D.D. TD 1.4.1	ISSUES				
PAPER: W					
CIRCULATION GENERAL		B	NEW FORMAT	AW	25 - 1 - 68
		A	COIL INDUCTION No. 27 WAS No. 22		13 - 3 - 50
			E.S.R., St.		10 - 6 - 39