## STD METERING AT PMB X's MULTIPLE TYPE SWITCHBOARDS (NOTE I) SCHEMES C2 AND D2 (NOTE 5)

## NOTES:-

- I. SECTION SWITCH B.E.C.B. MULTIPLE No. 9
  SECTION SWITCH B.E.C.B. No. 10
  SECTION SWITCH P.B.X. SA 7560
  SECTION SWITCH P.M.B.X?S IA AND IB
- 2. RESISTOR, COIL No.9 TO BE INSERTED IN SERIES WITH BATTERY SUPPLY TO METERING-UNIT No.3A AT B.E.C.B. No.10 INSTALLATIONS
- 3. LOCATION OF FUSE MOUNTINGS WILL VARY ACCORDING TO CIRCUMSTANCES AT INDIVIDUAL INSTALLATIONS
  THE FUSING ARRANGEMENTS SHOULD BE AS FOLLOWS:I-OAMP PER IO METERING UNITS No. 3A
  O-5 AMP PER MOUNTING No. 91551 (I.E. PER 3 METERS No. 2!---)

- 4. LABEL No. 359A ENGRAVED I-10
  LABEL No. 359B ENGRAVED II-20
  LABEL No. 359C ENGRAVED 21-30
  LABEL No. 364A ENGRAVED II-10
  LABEL No. 364B ENGRAVED II-20
  LABEL No. 364C ENGRAVED 21-30
- 5. FOR DETAILS OF METERING SCHEMES SEE DIAGRAM N 1010
- 6. SEE DIAGRAM N 1014 FOR DETAILS OF MOUNTING D91551 EQUIPPED FOR SCHEME C
- 7. WHERE NO APPARATUS RACK IS FITTED THE EARTH CONNEXION SHOULD BE MADE AT THE M.D.F OR SWITCHBOARD EARTH BUSBAR
- 8. ADDITIONAL EQUIPMENT AND WIRING SHOWN THUS\_\_\_ TO BE PROVIDED FOR SCHEME D2

	SCHEDULE OF APPARATUS		
	No. OFF		
DESCRIPTION	SCHEME C2	SCHEME D2	
METERING-UNIT No. 3A	I PER EXCHANGE LINE TO BE METERED	I PER EXCHANGE LINE TO BE METERED	
MOUNTING No. D 91477	I PER METERING-UNIT No. 3A		
METER NO. 150 A	NIL	I PER EXCHANGE LINE TO BE METERED	
METER, DUMMY No. 4	NIL	AS REQUIRED	
METER No.21A	AS REQUIRED. MAX 3 PER POSITION (EXCEPT AT BECH No.10 INSTALLATIONS)	AS FOR SCHEME C2	
METER No. 218	AS REQUIRED AT BECB No.10 INSTALLATIONS MAX 3 PER POSITION	AS FOR SCHEME C2	
MOUNTING D 91551	AS REQUIRED. MAX I PER POSITION	AS FOR SCHEME C2	
SWITCH, ROTARY CD 5022	I PER METER No. 21A OR No. 21B	AS FOR SCHEME C2	
KNOB, INSTRUMENT No. 8	I PER SWITCH ROTARY CD 5022	AS FOR SCHEME C2	
LABEL DUMMY No.1	AS REQUIRED	AS FOR SCHEME C2	
RESISTOR, COIL No. 9 240 n	I PER METERING-UNIT No. 3A AT B.E.C.B. No.10 INSTALLATIONS	I PER METERING-UNIT No.3A AT B.E.C.B No.10 INSTALLATIONS	
LABEL NO. 359 (A, B ORC) (NOTE 4)	AS REQUIRED	AS REQUIRED	
LABEL No. 364 (A,B ORC) (NOTE 4)	AS REQUIRED	AS REQUIRED	
INDUCTOR COIL No. 172 A	I PER EXCH LINE TO BE METERED AT NON THROUGH CLEA	ARING INSTALLATIONS	
FUSE FUSE MOUNTING	AS REQUIRED TO SUIT INDIVIDUAL INSTALLATIONS		

Р 0				
TELECOMMS				
HQRS	m			
PAPER :- W	S	<u> </u>	MU No. 3A WAS UM No. 1A MTG No. 165/ DELETED.	2- 8- 76
DISTN :-	2	Α	MTG D 914 77 ADDED . UPDATED MAN T.D. 7.2.1	5.8.10
GENERAL		17		10-3-60
	L	<u>v                                    </u>		<u> </u>

