



REAR VIEW SHOWING NUMBERING OF CONTACT SPRINGS AND TERMINALS



NOTE:-

Supplied with terminals 5 & 6 strapped.



WIRING SYMBOL

P.O.E.D. S BCH.	ISSUES			
PAPER : W				
CIRCULATION GENERAL	B	New Format	F.R.L.	6-10-67
	A	Strap 1-3 deleted.		10-12-65
		S1/1 F.E.Troke		16-6-64