NOTES:-

I.BATTERY SUPPLY TO U.A.A. TO BE MADE VIA A FUSE No. 36/I, FITTED NA FUSE MOUNTING No. 136A SCREWED TO WOODWORK ABOVE EXISTING FUSE MTG. FUSE TO SUPPLY 1 TO 4 UNITS.

- 2 WHERE OMISSION OF EXCH. PROHIBITION HAS BEEN AUTHORISED OMIT CONNEXION JKA (3) TO BT. No. 30 (4)
- 3 A LABEL MARKED UAA MODIFIED TO DGM. N714 TO BE FIRMLY ATTACHED TO UNIT. (USE LABEL WHITE No.398A)

RECOVER	PROVIDE
WIRES FROM INNER SPRINGS OF JKA TO b & C. OF INDICATOR NO. 2200A. INSULATE & THE BACK INTO FORM. TAG 3 OF JKA WIRES FROM DISCASE THE WIRES WIRE TO 4" OF S RELAY COIL IN U.A.A WIRES FROM DIS. CASE TO S.C. No. IOI ON SELECTED EXCH TERMIN. AT BOTH ENDS.	BT. No. 30 ADJACENT TO SC No. 101. IN SWBD. IN S

STRAPS ON	UAA No.45
1 — 8	7 — 12 17 — 19
3 - 5	'' ' '

P.O.E. D. S BCH.

PAPER: R

PAPER: K										 		
	S		,					•				
	Ä											
CIRCULATION:	ร	В	NEW	FORMAT.	MADE	RED	FL.R.			 	23. 11. 6	66
RESTRICTED	<u>S</u>	Α	NOTES	ADDED.	MINOR	AMENDA	MENTS	G.	A. A.	 	8.12.61	
KESIKIC IED			P.A.M	IARCHANT		53/2					21-10-5	55

TERMINATION OF INTER-P.B.X. PRIVATE CIRCUIT OR PRIVATE CIRCUIT. SWITCHBOARD CB.873

N714 ISSUE B

SIGNALLING GROUP C: G/AC IN; LOOP OUT.



