



NOTES:-

1. When recall delay is required, omit strap 17-26 in BC6A. Provide Delay Unit in accordance with Dgm Q516 issue D Sht 5. Utilise spare wire in multiple cable to connect DU lead to each telephone where recall is required. Connect DU lead from last station to terminal 29' in Relay Unit Q516.
2. For Earth One Line recall, remove strap between terminals T68 & T69,
3. KC spring-set operates on over-press of KXA & KXB.

P.O.E.D. S BCH.	ISSUE		
		PAPER - W	
CIRCULATION - GENERAL	A	STRAP BETWEEN BC17 & 26 OPTIONAL. DU LEAD ADDED. NOTE 1 CHANGED TO INCLUDE REFERENCE TO DELAY UNIT. <i>and jnd</i>	12.1.81
			ME/PD/1.2.2
		S1/3	11.7.67