

CIRCULATION

GENERAL

# TELEPRINTER WORKING AT NON-PANEL MOUNTED OFFICES. TG(L) 1084 POWER ARRANGEMENT FOR SUPPLY TO LOCALS OF RECEIVING RELAY FROM D.C. MAINS. 4-10-37.

RES. BULBS No. 11 WERE CUT OUT & RES. No. 1	17/10/41	A							
AMENDMENT									

W

